

Meeting January 9, 1991

1. Why ~~are~~ is Hart Crowser confident the system will work without a water level mgs. What data do they base this decision on then.
2. Has Hart Crowser considered the effect of the St. Joe on the hydraulics of the infiltration gallery
3. Product needs to be reanalyzed - lower detection limits - better define nature
4. Barrier Wall / Impermeable membrane - skimmer pump - less water to be pumped
5. Need a registered professional to approve the clean up plan as being appropriate for the site and to the best of their ability to clean up the site

USEPA SF



1420338